




## Option -PCB



### Column Arranged to Receive 1-1/2" Pipe Brace-

In order to provide additional structural reinforcement for the column and the sprayhead on a wash fountain, a pipe brace is inserted in the column to receive a 1-1/2" galvanized pipe (by others), which runs through the column ending at the sprayhead.

Please visit [www.acorneng.com](http://www.acorneng.com) for most current specifications.

⚠ WARNING: Cancer and Reproductive Harm - [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

